

# GRAFFITI

## Muestra

Lateral wall built in carbonated sandstone. Santa Maria la Mayor church. Alcañiz. Teruel. Spain.

---

## Causas de la patología

Mechanical anthropic action.

---

## Imagen de visu



**Autor:** Manuel Iglesias

**Descripción:** Carved figure, named below, (right) and schematic representation of a house (left) on the surface of an ashlar,

---

## Imagen detalle / macro



**Autor:** Manuel Iglesias

**Aumentos:** scale

**Descripción:** Detail of the house. The incision of the carving has slightly rounded edges suggesting certain antiquity.

---

## Bibliografía

ICOMOS-ICS (2008). Illustrated glossary on stone deterioration pattern.

[http://international.icomos.org/publications/monuments\\_and\\_sites/15/pdf/Monuments\\_and\\_Sites\\_15\\_ISCS\\_Glossary\\_Stone.pdf](http://international.icomos.org/publications/monuments_and_sites/15/pdf/Monuments_and_Sites_15_ISCS_Glossary_Stone.pdf)

ORDAZ, J., & ESBERT, R. (1988). Glosario de términos relacionados con el deterioro de las piedras de construcción. *Materiales de Construcción*, 38 (209): 39-45. doi: 10.3989/mc.1988.v38.i209.847

---

## Autor

Manuel Iglesias Campos. manuel.iglesias@cetec-patrimoni.com

Restorer

---

## Institución o Empresa

